

# CORNER RECORD


Agency Index Bk 23, Pg. 55  
Document Number 20210014

City of Rocklin County of \_\_\_\_\_ Placer \_\_\_\_\_, California  
Brief Legal Description Centerline Sweetwater Dr., Antelope Oaks Unit No. 2, Bk. N of Maps, Pg. 40

Sec. 18

## CORNER TYPE

## COORDINATES (Optional)



- ☐ Government Corner ☒ Control  
☐ Meander ☐ Property  
☐ Rancho ☐ Other

Date of Survey November 5, 2020

N. \_\_\_\_\_ E. \_\_\_\_\_  
Elevation \_\_\_\_\_  
Units ☐ Metric ☐ U.S. Survey Foot  
Horizontal Datum \_\_\_\_\_  
Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
Vertical Datum \_\_\_\_\_  
☐ Complies with Public Resources Code §§8801-8819  
☐ Complies with Public Resources Code §§8890-8902

T. 11 N., R. 7 E., M.D.B. & M.

PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:  
Corner/Monument: ☐ Left as found ☐ Established ☐ Rebuilt ☐ Pre-Construction  
☐ Found and tagged ☒ Reestablished ☐ Referenced ☒ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ See sheet #2 for description(s):

Replaced original found monuments per C.R. 23/45 on 11/05/2020 with countersunk survey spike and washer stamped LS 5914 based upon the ties established per C.R. 23/45 after the original monuments were destroyed as a result of construction.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on February 5, 2021

Signed [Signature] P.L.S. or R.C.E. No. 5914



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 22, 2021

and examined and filed FEBRUARY 24, 2021

Signed [Signature] P.L.S. or R.C.E. No. 8373

Title Deputy Co. Surveyor

County Surveyor's Comment



BOOK 23 OF CORNER RECORDS PAGE 55

